

## ACME TOOLINGS

### Quality lab

Description	Model	Make	Qty
CMM (CNC)	Contras G2	Carl Zeiss	1
CMM (CNC) & VMS	Inspect 322	Carl Zeiss	1
VMS (CNC)	INEXIV 4540	Nikon	1
CMM (Manual)	Micro Hite 3D	Tesa	1
VMS (Manual)	EV3020	Opus	1
Digital height guage	3T00019	Tesa	1
	9E202602	Tesa	1
Surface tester	302839	BOWERS	1
Hardness tester	CV - 600A	BOWERS	1
Supported with other all essential instruments which are periodically calibrated and maintained in good condition			